

General Environmental Incident Summary

Incident: 3760 **Date/Time Notice:** 5/23/2015 **DEM Incident No:**

Responsible Party: Ken's Sanitation

Date Incident: 5/22/2015 **Time Incident:** 1500 **Duration:**

County: Cass **Twp:** 139 **Rng:** 49 **Sec:** 1 **Qtr:**

Lat: 46.87682 **Long:** -96.81952 **Method:** Interpolation from map

Location Description: Main Ave 25th St Fargo ND, 58102

Submitted By: Hunter Hubrig

Affiliation: Fargo Cass Public Health

Address: 4630 15th Ave N

City: Fargo

State: ND

Zip:

Received By:

Contact Person:

PO Box 2127
Fargo, ND 58107

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Vehicle Accident

Description of Released Contaminant: Hydraulic Fluid

Volume Spilled: 50.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Ken's Sanitation truck bucket was up and hit railroad bridge while traveling underneath. While towing vehicle away uphill hydraulic fluid leaked out.

Risk Evaluation:

Approximately 5 gallons of hydraulic fluid entered storm drain. Floor dry was applied. Fargo Water Treatment Plant notified as precaution.

of Fatalities: 0

of Injuries: 0

Affected Medium: 02 - water

Potential Environmental Impacts:

Hydraulic fluid entered storm drain but unlikely to impact surface water.

Action Taken or Planned:

Fargo Street Dept and Fargo Fire Dept used floor dry on spilled area. Dike was built around storm drains. After allowing floor dry to absorb fluid, Fargo Street Dept picked up floor dry with street sweeper.

Wastes Disposal Location: At appropriate disposal location.

Agencies Involved: Local Fire Department, Local Law Enforcement

Updates

Date: 5/23/2015 ***Status:*** Reviewed - No Action Required

Author: Espe, Brady

Updated Volume:

Notes:

Local health district followed up on incident. No further followup needed.